

Перв. примен.

ШВКС.687281.005

Справ. №

ШВКС.687281.005 Э3

The diagram illustrates the wiring of a transition plate. It features four connectors: X4 (IDC-20) on the left, X1 (FDC-20) in the center, X2 (FPC01-20-S) on the top right, and X3 (FPC10-9-V) on the bottom right. Each connector has 20 pins numbered 1 to 20. Wires connect the pins as follows: X4 pin 1 to X1 pin 1, 2 to 2, 3 to 3, 4 to 4, 5 to 5, 6 to 6, 7 to 7, 8 to 8, 9 to 9, 10 to 10, 11 to 11, 12 to 12, 13 to 13, 14 to 14, 15 to 15, 16 to 16, 17 to 17, 18 to X2 pin 18, 19 to X2 pin 19, and 20 to X2 pin 20. Additionally, X1 pin 18 is connected to resistor R1 (330), and X1 pin 19 is connected to resistor R2 (330). Both resistors are connected to X2 pin 18.

Поз. обозначение		Кол.	Примечание
R1, R2	Резистор RC05L 3 331 J (330 Ом 0805)	2	
Разъемы			
X1	Вилка на плату FDC-20	1	
X2	Розетка FPC01-20-S	1	
X3	Розетка FPC10-9-V	1	
X4	Розетка IDC-20	1	

ШВКС.687281.005 Э3

Плата переходная
Схема электрическая
принципиальная

Лит.

Масса

Масштаб

Лист

Листов 1

Подп. и дата

Подп. и дата

Инв. № подл.

Изм. Лист № докум. Подп. Дата

Пров. Попов

Т. контр.

Н. контр.

Утв. Лукьянов